FIRMWARE HISTORY

INTRODUCTION

Evolis is conducting for many years a general policy to improve the quality and features of his printer range. This document describes modifications and improvements from original firmware release 1609 to the latest available from Evolis website version 1733 released on December 04th, 2017.

Related printers' models:

- **KM500B**
- **KM2000B**

SUMMARY

VERSION HISTORY 2

Firmware version – 1733 (F2C8) 2

Firmware version – 1609 2

VERSION HISTORY

04/12/2017

Firmware version – 1733 (F2C8)

Features:

- Add KO 1500 prints ribbon management.
- New feeder empty detection when feeder and bezel both enabled. #4349

Improvement:

- Empty and near empty Kytronics feeder status. #4353
- Ribbon remaining percentage accuracy.
- “Sis” sequence command.

BugFix(es):

- Recovery card stuck issue between Kytronics feeder and print module. #4515

01/05/2016

Firmware version – 1609

- Original firmware version.

EUROPE - MIDDLE-EAST - AFRICA
Evolis - 14 avenue de la Fontaine - ZI Angers-Beaucouzé
49070 Beaucouzé - France
T +33 (0) 241 367 606 - F +33 (0) 241 367 612
info@evolis.com

AMERICAS - Evolis Inc. - Fort Lauderdale - evolisinc@evolis.com
ASIA-PACIFIC - Evolis Asia Pte Ltd - Singapore - evolisasia@evolis.com
CHINA - Evolis China - Shanghai - evolischina@evolis.com
INDIA - Evolis India - Mumbai - evolisindia@evolis.com

www.evolis.com